DMV Lane Technician Observation Report

DMV Technician: Qui MACK P	Position Por 2			
Station: Wilm Date: $10-29-13$	Time: / . 5 5	ime: 1:55		
Vehicle Make: Hade Model ELANTVA		Year 2004		
GVWR: Fuel Type: 625 Registration Number: 620				
Auditor: Overdole - Covert Overt (circle one)				
	YES	NO	N/A	
1. Did technician check vehicle paper work and verify VIN numb	per?			
2. Was Emissions testing required?	V			
a) Was Emissions testing performed using OBD?	V			
b) Was Emissions testing performed using Analyzer Probe?				
c) Was Emissions testing performed using Paddle(s)?				
d) Was Emissions testing performed using Clip?				
3. Was Catalytic Converter inspection required?			V	
a) Was Catalytic Converter inspection performed?				
4. Was Fuel Tank pressure testing required?			V	
a) Was Fuel Tank pressure testing performed?				
5. Was Fuel Cap pressure testing required?			V	
a) Was Fuel Cap pressure testing performed?				
6. Is this test a Re-check from a prior failure?		V		
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiv	ver?			
New Castle and Kent Counties Only		V		
7. Was Two-Speed Idle testing required?				
a) Was Two-Speed Idle testing performed?				
Sussex County Only				
8. Was Curb Idle testing required?				
a) Was Curb Idle testing performed?				

Comment: K M HON 46 D74 V 857611				
1				
Lane Supervisor Signature:				

Revised 04/12/2013